

US Army corps Of Engineers Buffalo District 1776 Niagara Street Buffalo, New York 14207-3199

Notice to Navigation Interests

Notice No.	Date
Waterway	

Lake Ontario, New York

LRB-ON-TD-S

Condition of Federal Navigation Channel Port Ontario, Sodus, New York

- 1. Condition surveys performed within the Federal navigation Channel at Port Ontario, New York during the month of August 2002 indicate shoaling has reduced depths to those shown on the attached standard tabular form and channel condition drawings.
- 2. Soundings are in feet and referred to Low Water Datum (LWD) 243.3 above Mean Water Level (MWL) at Rimouski, Quebec (International Great Lakes Datum 1985).
- 3. Vessel operators are advised to use caution when navigating in this area.
- 4. Copies of the sounding print for Port Ontario, New Tork consisting of (1) sheet, 02S-PTO-1/1, at a cost of \$2.50 per sheet will be furnished upon receipt of a check in the full amount made payable to: United States Army Engineer District, Buffalo. Requests should be addressed to: District Commander, U.S. Army Engineer District, Buffalo, ATTN: NY/PA O&M Office, 1776 Niagara Street, Buffalo, New York 14207, requesting exact number or copies of sheets by file number. A point of contact and phone number must be indicated to facilitate response to the request. To obtain the Metadata and CADD files and view a color version of this map, point your web browser to http://www.lrb.usace.army.mil/waterways/survey/survey.html and locate the harbor on the table of harbors. This web page has been temporarily disabled, please check back later.
- 5. Buffalo district's point of contact in reference to the exact number of sheets, file number, and the availability of any later information pertaining to the area is Mr. Kelly L. Maccarone, Chief of the Survey Section, Buffalo District, and may be contacted by phone at 716-879-4285.

REPORT OF CHANNEL CONDITIONS (FOR CHANNELS LESS THAN 400 FEET WIDE) (ER-1330-2-316)

PAGE 2 OF 4 PAGES

DATE

TO: ACCOMPANY LOCAL NOTICE TO NAVIGATION INTERESTS, DATED

FROM: U.S. ARMY CORPS OF ENGINEERS, BUFFALO DISTRICT 1776 NIAGARA STREET, BUFFALO, NY 14207-3199 (716) 879-4292 FAX (716) 879-4356

RIVER/HARBOR NAME AND STATE				MINIMUM DEPTHS IN CHANNEL ENTERING			
PORT ONTARIO HARBOR , PORT ONTARIO, NEW YORK AUTHORIZED PROJECT				FROM SEAWARD LEFT RIGHT			
NAME OF CHANNEL	DATE OF SURVEY	WIDTH (feet)	LENGTH (feet)	DEPTH (feet)	OUTSIDE QUARTER (feet)	MIDDLE HALF (feet)	OUTSIDE QUARTER (feet)
(A) ENTRANCE CHANNEL.	AUGUST 2002	100	1200 (a)	8	7.1	7.5	6.6
(B) SALMON RIVER CHANNEL.	AUGUST 2002	100 – 85	450	6	6.0+	6.0+	6.0+
	=						

REMARKS: (a) LENGTH VARIES DEPENDING ON THE LOCATION OF THE 8 FOOT CONTOUR IN LAKE ONTARIO.



